



TELESCOPING FLAGPOLES

For Technical Support visit us at www.sunsetter.com/ownerscorner
or Call Toll Free 800-670-7071 • Fax 877-224-4944

Tube #3 Bottom Cap Replacement Instructions

Tools Needed: Phillips Screwdriver

Parts Supplied: Bottom Cap, Mounting Screws (qty 2)

WARNING: FAILURE TO FOLLOW THESE INSTRUCTIONS CAN RESULT IN PERSONAL INJURY! PLEASE READ THESE INSTRUCTIONS COMPLETELY BEFORE PERFORMING THIS PROCEDURE.

1. Remove the top three sections of the pole by holding in the bottom Spring Button while extending the section upwards and sliding the top three sections completely out of tube #4.
2. Remove the Bottom Cap mounting screws and remove the Bottom Cap.
3. Align the slot in the Bottom Cap with the track inside the tube and slide the new Bottom Cap into the tube.
4. Install the two new Bottom Cap mounting screws.
5. Place the top three sections of the pole back into tube #4. Lower them slowly until the Spring Button pops out of the hole in tube #4. Be sure to line up the slot in the Bottom Cap with the track on the inside of the tube.
6. Test the Flagpole for proper operation.

